



Date: 7/9/02
To: All Niles Dealers and Representatives
From: The Technical Support Department
Subject: Addendum to EZ-Crimp Tech Bulletin

Page 1 of 1

On 7/03/02 a Tech Bulletin was issued which detailed the possibility of EZ-Crimp RJ-45 connectors causing a short when used with the ZR-4630 Receiver, A4.6Ci Preamplifier, and IntelliPad Ci Systems. This short occurs when there is copper wire exposed at the end of the connector. This condition can be remedied by changing the blades in the crimping tool on a regular basis. This will provide a clean cut and greatly reduce the possibility of a short.

The Bomar part number for the replacement blades is: BD45000BL