

DATE: 11.03.2008

## RELEASE NOTES FOR BUILD 138F

Software Build Issues Fixed:

### New Features Added:

The firmware update program for IntelliFile 3 sets the default value of all wireless Zigbee devices, such as iRemote and iRemoteTS, to a new setting that improves RF communications.

The firmware update program now includes a summary screen at the end of the wizard mode that can print out the entire IntelliControl ICS system and the firmware versions in each product.

Thirty-one new devices have been added to the IR library and two devices have been updated in the RS-232 library. The IR library manager now allows for the conversion of files created by the IntelliFile2 system for the original IntelliControl. Installer can now convert their .lin files for use with the IntelliControl ICS system.

The Display keypad and iRemote have a new feature that allows the up and down arrows to cycle through characters when in text entry mode.

### User Interface Devices:

#### iRemoteTS

Improved overall operations, including Favorites for IM-Audio cards, functionality when in IR only mode for a home theater, and resets to zone 1 after changing RF settings.

Zigbee radio has higher value Clear Channel Assessment setting for better communication.

#### iRemote

Allow up/down keys to select characters in Edit Text entry mode.

Zigbee radio has higher value Clear Channel Assessment setting for better communication.

#### Display

Allow up/down keys to select characters in Edit Text entry mode.

#### ic2Remote

Zigbee radio has higher value Clear Channel Assessment setting for better communication.

### Source Card

#### IM-S-ESCNT

Improved overall functionality including, timeout issue when performing multiple letter searches (slowly) and when alpha search returns no match.

Playlist issue resolved from FP-1.

#### IM-S-REQST

Improved overall functionality including, timeout issue when performing multiple letter searches (slowly)

### GXR2

GXR2 now has factory default setting for all zones are enabled ON for GLOBAL/PARTY mode



### IntelliFile3

Numerous fixes that address functionality and reliability including setting unit ID on wireless devices.

Added reminder pop-up on the main screen for installers to check regularly for newer version of IntelliFile 3

### ICS Firmware Update

Firmware update sets the default value of Clear Channel Assessment setting for all Zigbee radio's and better communication.

Improved overall functionality including: adding summary screen at the end of Wizard mode that allows print-out and added recovery mode for Slave GXR2 back to Master.