



Date: 12/29/04
To: All Niles Dealers and Representatives
From: The Technical Support Department
Subject: IR Flasher blocking Covers

Page 1 of 1

It has come to our attention that the Niles 2004 Product Catalog lists the MF1VF and MF2VF MicroFlashers® with Visible Feedback as shipping with an elastomer blocking cover. Since installing a blocking cover on these products would negate the Visible Feedback feature, one is **not** included. The MF1, MF2, and MF1U MicroFlashers without the Visible Feedback feature are shipped with blocking covers as stated in the catalog.

Should you have any questions, please feel free to contact Niles Technical Support at 1-800-289-4434 between the hours of 8am and 7pm Eastern Time, Monday through Friday.